

STRAIGHTLINE **PERFORMANCE**

2007-11 Arctic Cat 1000 Y-Pipe
131-122 High Temp Black

Installation Instructions

- Remove the stock Y-Pipe; be sure to keep all stock springs and hardware; they will be reused. Check gaskets and replace in needed.
- Reinstall the Straightline Performance Y-Pipe in the reverse order of the removal.
- Apply lock tight and torque the bolts to factory specifications.
- Be sure the Straightline Y-Pipe has no manufacture defects. If the pipe has been run or used there will be **No Warranties** for fitment.

Clutching Requirements: No clutching is required, but recommended

Operating RPM: 7250-7350

Fuel Mapping: Fuel mapping is not required if the Y-pipe is the **only** performance enhancing addition.

Straightline Performance 15250 Hornsby St Forest Lake, MN 55025 651-466-0212
www.straightlineperformance.com

Technical questions please email tech@straightlineperformance.com



You Tube



Facebook @ straightlineperformanceinc

Youtube @ straightlineperfinc

Twitter @ straightlineperf